

ARC FLASH

Protect employees
from arc flash hazards.

MEETS NFPA 70E STANDARD



Protect your employees from arc flash hazards. National Electric Code Standards require that labels be posted on or near switch-boards, power boards, control panels and motor control centers. Protect your employees from electric shock, burns, fires, and explosions by posting NMC's arc flash labels close to the potential hazard.

Pressure sensitive vinyl is ideal for affixing directly to equipment or machinery. Convenient size makes them easy to place close to the potential hazard. Need a custom arc flash label? NMC will create a unique label based on your specific message.

Related Products

- Machine Labels
- Graphic Signs
- Electrical Lockout Tagout, Tags, Lockouts, Kits and Centers
- Glow Safety Labels
- NMC Tuff Guard
- Unique Arc Flash Labels

Specifications

- 3" x 5"
- Pressure Sensitive Vinyl
- 5/pack


Features

- High Quality Vinyl with Adhesive Backing
- Protect employees from arc flash Hazards by posting labels on or near switchboards, power boards, control panels and motor control centers.
- NFPA 70E instructs employers to conduct an arc flash analysis to determine the amount of thermal energy that could be generated in an arc flash incident. The information is then used to define a flash protection boundary around the potential source, and to determine the level of flame-resistant apparel and other personal protection equipment required.

View all of our Arc Flash Labels at
nationalmarker.com

⚠ DANGER

Arc Flash and Shock Hazard
Appropriate PPE and Tools Required when working on this equipment




3 x 5 DGA61AP

⚠ DANGER

Arc Flash and Shock Hazard.
Appropriate PPE Required.
Follow all safety procedures and wear proper PPE in accordance to NFPA 70 E.
Failure to comply can result in serious injury or death.

3 x 5 DGA58AP

⚠ DANGER PELIGRO ⚠

<p>Arc Flash and Shock Hazard</p> <p>Do not operate controls or open covers without appropriate personal protection equipment. Failure to comply may result in injury or death!</p> <p>Refer to NFPA 70E for PPE requirements.</p>		<p>Riesgo de Arco Elctrico y Descarga</p> <p>No opere mandos o abra cubiertas sin el equipo de protección personal apropiado Fracso de cumplir puede terminar en herida o muerte.</p> <p>Referencia a NFPA 70E para requisitos de EPP</p>
---	---	--

3 x 5 DGA63AP

⚠ DANGER

Arc Flash and Shock Hazard.
Follow all requirements in NFPA 70 E.
For safe work practices and for personal protective equipment.

3 x 5 DGA59AP

⚠ DANGER

Arc Flash Hazard.
Appropriate PPE Required.
Failure To Comply Can Result in Death or Injury. Refer to NFPA 70 E.

3 x 5 DGA60AP

⚠ DANGER


Arc Flash & Shock Hazard
Appropriate PPE Required

Flash Hazard Category _____	Min. Arc Rating (cal/cm ²) _____	Flash Protection Boundary _____	Limited Approach Boundary _____	Restricted Approach Boundary _____	Prohibited Approach Boundary _____
WIC Shock Hazard When: _____		Equipment ID: _____			

FLASH PPE	<input type="checkbox"/> FR shirt	<input type="checkbox"/> Hard hat	<input type="checkbox"/> Leather gloves	SHOCK PPE
<input type="checkbox"/> Cotton underwear	<input type="checkbox"/> FR pants	<input type="checkbox"/> Face shield	<input type="checkbox"/> Leather shoes	
<input type="checkbox"/> T-shirt	<input type="checkbox"/> FR coverall	<input type="checkbox"/> Ear protection	<input type="checkbox"/> Wristing	
<input type="checkbox"/> Long-sleeve shirt	<input type="checkbox"/> Flash suit	<input type="checkbox"/> Safety glasses	<input type="checkbox"/>	
<input type="checkbox"/> Long pants	<input type="checkbox"/> Flash hood	<input type="checkbox"/> Safety goggles	<input type="checkbox"/>	

3 x 5 DGA65AP

⚠ DANGER PELIGRO ⚠

<p>Arc Flash Hazard</p> <p>Do not operate controls or open covers without appropriate personal protection equipment. Failure to comply may result in injury or death!</p> <p>Refer to NFPA 70E for PPE requirements.</p>		<p>Riesgo de Arco Elctrico</p> <p>No opere mandos o abra cubiertas sin el equipo de protección personal apropiado Fracso de cumplir puede terminar en herida o muerte.</p> <p>Referencia a NFPA 70E para requisitos de EPP</p>
---	--	---

3 x 5 DGA62AP

⚠ WARNING

Arc Flash and Shock Hazard
Appropriate PPE Required

Flash Hazard Boundary _____ cal/cm² Flash Hazard at 18 inches PPE Level, _____

Shock hazard when Cover is _____

Limited Approach - _____

Restricted Approach - _____


Prohibited Approach - _____

Equipment Name: _____

3 x 5 WGA18AP

⚠ WARNING

Arc Flash and Shock Hazard
Appropriate PPE and Tools Required when working on this equipment



3 x 5 WGA35AP

⚠ WARNING

Arc Flash Hazard
Appropriate PPE Required


Flash Protection Boundary _____	Flash Hazard Category _____	Min. Arc Rating (cal/cm ²) _____
---------------------------------	-----------------------------	--

Flash PPE	<input type="checkbox"/> FR shirt	<input type="checkbox"/> Hard hat	<input type="checkbox"/> Leather gloves
<input type="checkbox"/> Cotton underwear	<input type="checkbox"/> FR pants	<input type="checkbox"/> Face shield	<input type="checkbox"/> Leather shoes
<input type="checkbox"/> T-shirt	<input type="checkbox"/> FR coverall	<input type="checkbox"/> Ear protection	<input type="checkbox"/>
<input type="checkbox"/> Long-sleeve shirt	<input type="checkbox"/> Flash suit	<input type="checkbox"/> Safety glasses	<input type="checkbox"/>
<input type="checkbox"/> Long pants	<input type="checkbox"/> Flash hood	<input type="checkbox"/> Safety goggles	<input type="checkbox"/>

Equipment ID: _____

3 x 5 WGA36AP

⚠ WARNING ADVERTENCIA ⚠

<p>Arc Flash Hazard</p> <p>Do not operate controls or open covers without appropriate personal protection equipment. Failure to comply may result in injury or death!</p> <p>Refer to NFPA 70E for PPE requirements.</p>		<p>Riesgo de Arco Elctrico</p> <p>No opere mandos o abra cubiertas sin el equipo de protección personal apropiado Fracso de cumplir puede terminar en herida o muerte.</p> <p>Referencia a NFPA 70E para requisitos de EPP</p>
---	---	---

3 x 5 WGA34AP

⚠ WARNING

Arc Flash Hazard.
Appropriate PPE Required.
Failure To Comply Can Result in Death or Injury. Refer to NFPA 70 E.

3 x 5 WGA17AP

⚠ WARNING

Arc Flash Hazard
Appropriate PPE Required

Flash Protection Boundary _____	Flash Hazard Category _____	Min. Arc Rating (cal/cm ²) _____
---------------------------------	-----------------------------	--

Flash Protection Equipment

- Cotton underwear
- FR shirt and pants plus FR coverall
- Flash suit hood and hard hat
- Safety glasses or goggles
- Hearing protection
- Leather gloves and shoes

Equipment ID: _____

3 x 5 WGA37AP

⚠ WARNING ADVERTENCIA ⚠

<p>Arc Flash and Shock Hazard</p> <p>Do not operate controls or open covers without appropriate personal protection equipment. Failure to comply may result in injury or death!</p> <p>Refer to NFPA 70E for PPE requirements.</p>		<p>Riesgo de Arco Elctrico y Descarga</p> <p>No opere mandos o abra cubiertas sin el equipo de protección personal apropiado Fracso de cumplir puede terminar en herida o muerte.</p> <p>Referencia a NFPA 70E para requisitos de EPP</p>
---	---	--

3 x 5 WGA33AP

Size	Qty	1 - 24	25+
3" x 5"	5/pk	\$10.07	\$9.07